

567 E. Hudson St. Columbus, OH 43211 614/298-2000

OHIO HISTORIC INVENTORY

RPR Number:

2. County Butler 5. His	oric or Other Name(s) East Dining Hall		BUT-0251 8-01
		5. Historic or Other Name(s) East Dining Hall	
6. Specific Address or Location North Fisher Drive	19a. Design Sources	35. Plan Shape Rectangular	2. County Butler
6a. Lot, Section or VMD Number	20. Contractor or Builder Carl Conradt & Sons, Hamilton, Ohio 21. Building Type or Plan Other Building Type 22. Original Use, if apparent	36. Changes associated with 17/17b Dates: 17. Original/Most significant construct	
7. City or Village Oxford	College/University	37. Window Type(s) Steel	Еа
9. U.T.M. Reference Quadrangle Name: Oxford 16 695524 4375653	23. Present Use College/University	Casement 38. Building Dimensions	resent or H Ist End
Zone Easting Northing 10. Classification: Building	24. Ownership Public 25. Owner's Name & Address, if known Miami University	39. Endangered? NO By What?	4. Present or Historic Name(s. East End Building
11. On National Register? NO 13. Part of Established Hist. Dist? NO	Oxford, Ohio 45056 26. Property Acreage	40. Chimney Placement No chimney observed	
15. Other Designation (NR or Local)	27. Other Surveys 28. No. of Stories	41. Distance from & Frontage on Road 51. Condition of Property:	
16. Thematic Associations: University	One story 29. Basement? 30. Foundation Material Concrete slab	Good/Fair 52. Historic Outbuildings & Dependencies Structure Type	\parallel
17. Date(s) or Period 17b. Alteration Date 1954 18. Style Class and Design	ate(s) 31. Wall Construction Metal/steel frame	Date	
None 18a. Style of Addition or Elements(s)	32. Roof Type Multiple gable Roof Material Standing seam (metal)	Associated Activity	
19. Architect or Engineer	33. No. of Bays 14 Side Bays 15 34. Exterior Wall Material(s)	53. Affiliated Inventory Numbers: Historic (OHI)	
	Sheet metal	Archaeological (OAI)	1_

42. Further Description of Important Interior and Exterior Features (Continued on Reverse if Necessary)

The East End building is a prefabricated steel structure built on a reinforced concrete slab foundation. Windows are the original hopper steel casement sash, the siding is sheet metal panels laid vertically, and the roof is standing seam metal. Off center in the facade is an entrance porch with flat roof and square wood posts at the ends, a modification from the original three sets of paired posts. The porch shelters a pair of double entry doors set within a projecting wood-framed vestibule. There are three gables on side elevations, showing the original construction of the building in three rectangular gabled sections. The east side remains as originally built, with 15 steel casement windows. On the west side, garage and man doors have been added to accommodate the current use, which appears to be storage.

43. History and Significance (Continue on Reverse if necessary)

The East End Dining Hall was built at a cost of \$159,600 in 1954 to provide a temporary dining hall for the East Quadrangle dormitories, including Collins, McBride, and the Pines. It also served Dennison and Dorsey Halls after they were constructed. The dining capacity was for 700. Apparently used for storage today, the building is unusual on the Miami campus because of its prefabricated steel construction.

44. Description of Environment and Outbuildings (See #52)


The building is located on the East campus of Miami University, in an area of large dormitories. To its east is a large wooded area.

45. Sources of Information

Miami University Archives, Building Record, building files; The Miami Alumnus, 'Halls for Miami Men,' September 1, 1955.

46. Prepared By: **Judy** 49. PIR Reviewer:

6. Specific Address or Location **North Fisher Drive**



54. Farmstead Plan :

Door Selection:

Two doors symmetrical

Door Position:

Protruding

Orientation: Lateral axis

Symmetry:

Bilateral asymmetry

Report Associated With Project:

NADB #:





1. No. BUT-02518-01	4. Present Name(s) East End Building	8-01
2. County Butler	5. Historic or Other Name(s) East Dining Hall	0251
42. Further Description of Important Interior and Exterior Features (Con't)		
43. History and Significance (Con't)		
44. Description of Environment and Outbuildings (Con't)		1
45. Sources (Con't)		-